# Janus-Ozy-SDR1000 on dummy load 50 ohms, 192 KHz

# Edirol FA 66-SDR1000 on dummy load 50 ohms, 192 KHz

## Janus-Ozy-SDR1000 + XG2, 192 KHz

## Edirol FA 66-SDR1000 + XG2, 192 KHz

Janus-Ozy with input not connected, SDR 1000 on, 192 KHz

Edirol FA 66 with input not connected, SDR1000 on, 192 KHz

Janus-Ozy with input not connected, SDR1000 off, 192 KHz

Edirol FA 66 with input not connected, SDR1000 off , 192 KHz